

Date: 03/13/15

Situation:

Some customers have reported a very loud locate tone from an EN2 pbs. The indications are that it happens only on one button at a time and only on channel A and only on SP1 installations.

Solution:

EN2M firmware version 4.14 addresses this without regard to the actual cause. After installation, it corrects the issue immediately if/when it happens.

Polara Engineering, Inc.
9153 Stellar Court
Corona, CA 92883
(714) 521-0900
www.polara.com